

Stephen E. Hedges Site Vice President

May 5, 2010

WO 10-0036

U. S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, DC 20555

Subject:

Docket No. 50-482: License Event Report 2010-006-00, Manual

Reactor Trip due to Trip of Main Feedwater Pump

### Gentlemen:

The enclosed Licensee Event Report (LER) 2010-006-00 is being submitted pursuant to 10 CFR 50.73(a)(2)(iv)(A) regarding an Engineered Safety Features Actuation and subsequent reactor trip at Wolf Creek Generating Station.

Commitments made by Wolf Creek Nuclear Operating Corporation in the enclosed LER are identified in the Attachment to this letter.

If you have any questions concerning this matter, please contact me at (620) 364-4190, or Mr. Richard D. Flannigan at (620) 364-4117.

Sincerely,

Stephen E. Hedges

SEH/rlt

Attachment Enclosure

cc: E. E. Collins (NRC), w/a, w/e

G. B. Miller (NRC), w/a, w/e

B. K. Singal (NRC), w/a, w/e

Senior Resident Inspector (NRC), w/a, w/e

IE22

# LIST OF REGULATORY COMMITMENTS

The following table identifies those actions committed to by WCNOC in this document. Any other statements in this submittal are provided for information purposes and are not considered to be regulatory commitments. Please direct questions regarding these commitments to Mr. Richard Flannigan at (620) 364-4117.

REGULATORY COMMITMENT	DUE DATE/EVENT
The evaluation of the results from the Hardware Failure Analysis will be completed.	06/30/2010

NRC FORM 366 U.S. NUCLEAR REGULATORY								APPROVED BY OMB: NO. 3150-0104 EXPIRES: 08/31/2010									
(9-2007)  LICENSEE EVENT REPORT (LER)								Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Records and FOIA/Privacy Service Branch (T-5 F52), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to infocollects@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.									
1. FACILITY NAME WOLF CREEK GENERATING STATION							2. [	. DOCKET NUMBER 3. PAGE 05000 482 1 OF 3									
	4. TITLE  Manual Reactor Trip due to Trip of Main Feedwater Pump																
5. E	VENT D	ATE	6. l	ER NU	JMBEF	₹	7. R	EPORT D	ATE			8.	OTHER FA	CILITIES	INVOL	.VED	
MONTH	DAY	YEAR	YEAR	SEQUE NUM	ENTIAL IBER	REV NO.	MONTH	DAY	YEAF		FACILITY	NAME				05000	
03	80	2010	2010	- 00	)6 -	00	05	05	201		FACILITY	NAME				05000	
9. OPER	ATING I	MODE	11.	. THIS	REPO	RT IS	SUBMITTE	ED PURSI	UANT T	ΌΤ	HE RE	QUIREME	NTS OF 10	CFR§:	(Check	all that a	pply)
1 20.2201(b) 20.2201(d) 20.2203(a)(1) 20.2203(a)(2)(i) 20.2203(a)(2)(ii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iv) 42 20.2203(a)(2)(v) 20.2203(a)(2)(v) 20.2203(a)(2)(vi)					☐ 20.2203(a)(3)(i) ☐ 20.2203(a)(3)(ii) ☐ 20.2203(a)(4) ☐ 50.36(c)(1)(ii)(A) ☐ 50.36(c)(1)(ii)(A) ☐ 50.36(c)(2) ☐ 50.46(a)(3)(ii) ☐ 50.73(a)(2)(i)(A) ☐ 50.73(a)(2)(i)(B)				□ 50.73(a)(2)(i)(C)       □ 50.73(a)(2)(vii)         □ 50.73(a)(2)(ii)(A)       □ 50.73(a)(2)(viii)         □ 50.73(a)(2)(ii)(B)       □ 50.73(a)(2)(viii)         □ 50.73(a)(2)(iii)       □ 50.73(a)(2)(ix)(x)         □ 50.73(a)(2)(iv)(A)       □ 50.73(a)(2)(x)         □ 50.73(a)(2)(v)(A)       □ 73.71(a)(4)         □ 50.73(a)(2)(v)(B)       □ 73.71(a)(5)         □ 50.73(a)(2)(v)(C)       □ OTHER         □ 50.73(a)(2)(v)(D)       Specify in Abstract					(B) A)			
													. , , ,		or in NI	RC Form 3	66A
						1	2. LICENS	SEE CON	TACT F	OR	THIS L	ER					
FACILITY NAME Richard D. Flannigan, Manager Regulatory Affairs							-					120) 36		(Include Are	a Code)		
			13. COM	PLETE	ONE	LINE F	FOR EACI	н сомро	NENT	FAIL	LURE D	ESCRIB	D IN THIS	REPOR1	Г		
CAU	SE	SYSTEM	сомро	NENT	MAN			RTABLE EPIX	C	CAUS	SE	SYSTEM	COMPONEN		NU- URER		RTABLE EPIX
В	,	SJ	FC	V	G0	80		Y									
14. SUPPLEMENTAL REPORT EXPECTED									KPECTED	MON	ITH	DAY	YEAR				
☐ YES (If yes, complete 15. EXPECTED SUBMISSION DATE) ☐ N								] N(	0		MISSION DATE				l		
ABSTRA	CT (Lim	iit to 1400	spaces,	i.e., ap	proxim	ately 1	15 single-s	paced typ	ewritter	ı line	es)						

On 3/8/2010, Wolf Creek Generating Station (WCGS) was at 42 percent power during a reactor startup when the "A" main feedwater (MFW) pump tripped at 0332 CST. The control room operators manually tripped the reactor due to the decreasing steam generator levels. All control rods fully inserted and the Reactor Trip System and the Engineered Safety Feature Systems performed as expected. The cause of the MFW pump trip was a failed servo in the MFW control circuitry.

Emergency boration was actuated when reactor coolant system (RCS) temperature dropped below 550 degrees Fahrenheit. Emergency boration was secured at 0404 CST on 3/8/2010 when RCS temperature was raised to greater than 550 degrees Fahrenheit.

The safety significance of this event is low. This event is bounded by analyses as reported in the WCGS Updated Safety Analysis Report (USAR) Section 15.2.7, "Loss of Normal Feedwater Flow." There were no adverse effects on the health and safety of the public.

LICENSEE EVENT REPORT (LER)

EIOZITOZZ ZVZIVI (ZZIV)							
1. FACILITY NAME	2. DOCKET	(	3. PAGE				
WOLF CREEK GENERATING STATION	05000 482	YEAR 2010	SEQUENTIAL NUMBER	REV NO.	2	OF	3

### PLANT CONDITIONS PRIOR TO EVENT

MODE 1 Power Level – 42 percent

#### EVENT DESCRIPTION

On 3/8/2010 the Wolf Creek Generating Station (WCGS) was in the process of power ascension at approximately 42 percent power. The "B" main feedwater (MFW) pump [EIIS Code: SJ-P] was being warmed in the process of being placed in service, but was not providing flow to the steam generators (SG). At 0332 CST the "A" MFW pump automatically tripped. With no feedwater supply to the steam generators (SG) [EIIS Code: SG], water level in the steam generators began decreasing and the Control Room staff manually tripped the reactor at 0333 CST.

The MFW pump tripped due to a failed servo valve [EIIS Code: JK-FCV] in the main feedwater speed control system. The servo failed when it was in the open position, causing the low pressure and high pressure control valves to become full open. This resulted in more steam being admitted to the feedwater turbine when there was no demand for it. The speed of the feedwater turbine increased beyond its overspeed set point, resulting in a trip of the MFW pump.

The reactor was manually tripped due to the decreasing SG level, prior to the automatic trip set point being reached. All control rods fully inserted and all safety equipment performed as designed. The Reactor Trip System (RTS) and the Engineered Safety Feature Actuation System (ESFAS) [EIIS Code: JE] performed as required. The motor-driven auxiliary feedwater (AFW) pumps [EIIS Code: BA] started due to the loss of the MFW pump and the turbine-driven AFW pump started due to the loss of the resultant Low SG level.

Emergency boration was initiated at 0341 CST per procedure EMG ES-02, "Reactor Trip Response," when the reactor coolant system (RCS) temperature decreased below 550 degrees Fahrenheit. This was a result of the actuation of auxiliary feedwater (AFW) and the lack of decay heat with the reactor power at 42 percent. Emergency boration was secured at 0404 CST when RCS temperature was raised to greater than 550 degrees Fahrenheit, by throttling AFW flow. The lowest RCS temperature reached following the reactor trip was 544 degrees Fahrenheit.

# BASIS FOR REPORTABILITY

The reactor trip and subsequent actuation of ESFAS instrumentation described in this event is reportable per 10 CFR 50.73(a)(2)(iv)(A), which requires reporting of "Any event or condition that resulted in manual or automatic actuation of any of the systems listed in paragraph (a)(2)(iv)(B) of this section." Paragraph (B)(1) of 10 CFR 50.73(a)(2)(iv) includes "Reactor protection system (RPS) including: reactor scram or reactor trip." Paragraph (B)(6) of 10 CFR 50.73(a)(2)(iv) includes "PWR auxiliary or emergency feedwater."

J.S.	NUCLEAR	REGULATORY	COMMISSION

LICERSEL EVENT INEFORT (LEIN)							
1. FACILITY NAME	2. DOCKET		LER NUMBER	3. PAGE			
WOLF CREEK GENERATING STATION	05000 482	YEAR	SEQUENTIAL NUMBER	REV NO.	3	OF	a
THE STATE OF THE S	100000 402	2010	006	00	Ŭ	٥,	J

### **ROOT CAUSE**

The cause of the MFW pump tripping is a failed servo valve in the main feedwater speed control system. A Hardware Failure Analysis is investigating the exact cause for the servo failure. The servo valve is a device that takes an electrical signal and converts it to mechanical signal. The servo ports hydraulic oil to the bottom side of the pilot valve that controls the position of the secondary operating cylinder, which then controls the position of the low pressure (LP) and high pressure (HP) control valves for the feedwater turbine. The servo failed when it was in the open position, causing the pilot valve to travel full open, and the LP and HP control valves to become full open. This resulted in more steam being admitted to the feedwater turbine when there was no demand for it. The speed of the feedwater turbine increased beyond its overspeed set point, resulting in the trip of the MFW pump.

### **CORRECTIVE ACTIONS**

A Hardware Failure Analysis is in process to determine the the most probable cause of the servo failure. The evaluation of the results of the analysis will be completed by 6/30/2010. This evaluation will determine if additional actions are needed to prevent recurrence.

The servo valve was replaced and retested satisfactorily on 3/9/2010.

Action has been taken to replace the servo valve on a 3-year frequency.

# SAFETY SIGNIFICANCE

The safety significance of this event is low. This event is analyzed as reported in WCGS Updated Safety Analysis Report (USAR) Section 15.2.7, "Loss of Normal Feedwater Flow." Results of the analysis show that a loss of normal feedwater does not adversely affect the core, the reactor coolant system, or the steam system, since the auxiliary feedwater capacity is such that reactor coolant water is not relieved from the pressurizer relief or safety valves.

There were no adverse effects on the health and safety of the public.

#### OPERATING EXPERIENCE/PREVIOUS EVENTS

LER 2010-005-00 described a reactor trip due to a trip of a main feedwater pump caused by the failed transfer of an invertor to its alternate power supply.

LER 2009-001-00 described a reactor trip due to a Main Feedwater Regulating Valve (MFRV) closure in response to failures of the primary and secondary fuses for the Westinghouse 7300 control card frame that contained the associated control cards for the MFRV.

LER 2004-002-00 described a reactor trip due to a MFRV closure caused by the valve plug in the MFRV separating from the valve stem.